


Parts needed to mount the PK-4 extrusion




Tools needed for mounting:

- mounting adhesive
- drill

NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure. More mounting procedures and related accessories can be found at klusdesign.com.




В

Inspiring Solutions

KLUŚ





Inspiring Solutions

KLUŚ