



Parts needed to mount the STOS-ALU extrusion











Exrusion (A)

End caps (B)

Cover (C)

LED strip (D)

Clip (E)



Mounting track TEST-74 (G)

Tools needed for mounting:

- drill
- screwdriver
- screws

NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure. More mounting procedures and related accessories can be found at klusdesign.com

www.KlusDesign.com 1



 ${f 1}$. Drill mounting holes in the mounting track (G). **2.** Attach the mounting track (G) with screws and insert the clips (E). Ε **3.** Mount the LED strip (D), insert the cover (C), and then insert the end cap (B). **4.** Attach the extrusion (A) to the mounting track (G) and connect power. D C В

www.KlusDesign.com 2