KLUŚ **Inspiring Solutions**

Parts needed to mount the TETRA-78 extrusion

Extrusion (A)

Mounting track (B)

Extrusion end cap (C)

Mounting track end cap (D)

Cover (F)

LED strip (G)

Clip (H)

Tools needed for mounting:

- drill
- screwdriver
- hand saw
- Allen wrenches (dia. 0.11", dia. 0.19")

NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure.
More mounting procedures and related accessories can be found at klusdesign.com

KLUŚ **Inspiring Solutions**

1. Mount the LED strips (G), insert covers (F), and then insert the end cap (C). Feed the power cable.

A

G

F

C

2. Drill mounting holes in the surface and mounting track (B).

B

3. Attach the mounting track with screws (B). Insert clips (H) into it.

B

H

4. Connect power and snap the extrusion (A) into the mounting track (B).

B

A